

Procedure: C-A-OCR-SHP-OSH

Revision: 01

Revision Date: 05/25/04

COLLIDER-ACCELERATOR DEPARTMENT

Title: Operational Control Record, Shops							
Preparer: E. Lessard, R. Karol							
Group: ESH&Q							
		<u>Approvals</u>					
		Signature on File	Date:				
ES	ESH&Q Division Head						
		Date:					
Co	Collider-Accelerator Department Chairman						
	(Indicate additional signatures)						
Y □	N x	FS Representative:	Date:				
	X	Radiological Control Coordinator:	Date:				
	X	Chief ME:	Date:				
	X	Chief EE:	Date:				
X		ESH Coordinator: Signature on File	Date:				
	X	QA Manager:	Date:				

□ x Other: _____ Date: _____

C-A OSH OPERATIONAL CONTROLS RECORD

Operational Controls Record	Completed By: R. Karol
For Occupational Safety and Health Hazards	
	Date: May 25, 2004
	•

1. Operations:

The shop operations are located in various buildings at the accelerator complex managed by the Collider-Accelerator Department. The shops support the fabrication and maintenance of equipment, supplies and components used throughout the department. The machines utilized in the shops include milling machines, lathes, drill presses, band and table saws, grinders, shears, sanders, punches, breaks, benders, welding, brazing, soldering, grit blasters and parts cleaners. Magnet refurbishment work is also conducted in Building 922, where worn or damaged magnet components are repaired or replaced.

2. Activities:

- Small-scale fabrication, assembly, maintenance, repair, and cleaning of metal, plastic and fiberglass equipment and parts
- Soldering, metal cleaning, silver plating, coil maintenance, and cooling water hose and fitting repair

3. Controls – Sub-Systems, Operations, Safety Review and Personal Protective Equipment, Emergency Response:

All controls at the C-A complex are under a <u>Formal Conduct of Operations</u> (CO) and are described in detail in the <u>C-A Operational Procedures (OPM)</u>. Safety significant procedures included in the C-AD OPM include:

- **Sub-system Controls**: <u>Chapter 8</u>: Subsystems, Rad- Storage,-Chipmunks,-Fencing, Experimental Areas, Water, Waste
- Operational Controls: OPM Chapter 2 LOTO, Maintenance, Work Planning
- Safety Review and Personnel Protective Equipment: <u>OPM Chapter 9</u> Radiation Safety, ESH Committees, ESH Review, ALARA, Safety Inspection, Cryogenic Safety
- Emergency Response Controls: OPM Chapter 3, Emergency Procedures

4. Maintenance:

- OPM Chapter 2 LOTO, Maintenance, Work Planning
- OPM Chapter 7, Cryogenic Operations
- OPM Chapter 8 Subsystems, Rad- Storage,-Chipmunks,-Fencing, Experimental Areas, Water, Waste
- <u>Group Procedures</u> Collider-Accelerator Department, Specific Group Procedures

5. Actions to be Taken if Controls Fail:

- <u>CO Chapter 4</u> Communications
- <u>CO Chapter 6</u> Investigation of Abnormal Occurrences
- <u>OPM Chapter 3</u> Emergency Procedures
- OPM Chapter 10 Occurrence Reporting

6. Records:

- <u>CO Chapter 10</u> Independent Verification
- <u>CO Chapter 11</u> Logkeeping
- OPM Chapter 13 Quality Assurance
- **7. Responsibilities**: (a) to ensure controls are in place; (b) to ensure controls keep working; (c) to take action when controls fail; (d) to create and keep records relative to operational controls
 - R2A2s
 - <u>OPM Chapter 1</u> Policies for Authorization, Training, Environment, Safety, Procedures, Minors, Visitors
 - <u>CO Chapter 1</u> Organization and Administration

Name	Responsibility
Responsible and authorized personnel are listed and maintained in the C-A Operational Procedures Manual	OPM Chapter 1 - Authorization
	OPM 1.11 - Department Requirements for Interaction with C-A
	OPM 1.10 - Occurrence Reporting and Processing of Operations Information

8. Training:

Name	Training	Training Policy
Training data is maintained in BTMS	See specific Job Training Assessments (JTAs) in BTMS	OPM 1.12 – Training and Qualification Plan